





# **Little Apple Cars**



# Automobile Status Report

Prepared For

**INVENTORY: R53737C** 



2015 Toyota PRIUS

Date February 09, 2024

VIN JTDKN3DUXF0466925

Mileage 144788

RO# 6070630

Service Advisor

James Cook jrocktundra@gmail.com



# Little Apple Cars Service Commitment

# Excellence at every turn... and every straightaway

Our dealership's primary goal is to satisfy every customer at every opportunity. You visit our service department regularly, and we have developed a number of ways to make your visit more comfortable and informative. We know that you want straight answers, and that's the only way we will deliver it to you.

We understand that your knowledge of your vehicle and its necessary repairs is probably not on par with the understanding that your technician has. In order to be sure that his findings and reporting is as clear and concise as possible, we use this Vehicle Information Booklet as a tool to help us communicate your vehicle's condition to you.

Our technicians are the most qualified to work on your vehicle. They have trained extensively, and partake in continuing education regularly to be sure that they are up to date on any changes and improvements handed down from the manufacturer. Our service advisors strive to make your experience with us a pleasant one. They are here to attend to your automotive needs as well as communicate effectively with your technician and you.

Please make yourself comfortable in our waiting area. Watch some TV, use your laptop with our free WI-FI access or just relax and enjoy the quiet. Our courtesy shuttle can take you shopping, to a movie or home if you prefer.

We appreciate your business and will continue to strive for excellence in everything we do for you.

# Multi-Point Inspection Form

RO# 6070630 INVENTORY: R53737C

VIN JTDKN3DUXF0466925

Advisor James Cook Technician Matt Fisher Created On 2/9/2024

Checked and OK at this time	May Require Future Attention	Requires immediate attention
ROAD TEST		FUNCTIONAL
BRAKE OPERATION PASS	🔳   н	ORN <u>PASS</u>
ENGINE OPERATION PASS	🔳 🔠 п	RES <u>PASS</u>
DRIVETRAIN OPERATION PASS	Lf	= <u>9</u>
TRANSMISSION OPERATION PASS	RI RI	F <u>9</u>
LIGHTS		R <u>7</u>
TAIL LAMPS PASS	R	R <u>Z</u>
HEAD LAMPS PASS	SI	EAT BELTS <u>PASS</u>
STOP LAMPS PASS		/INDSHIELD <u>PASS</u>
TURN SIGNALS PASS	P	ARKING BRAKE <u>PASS</u>
SIDE MARKER LAMPS PASS	<b>                                   </b>	/IPERS AND WASHERS <u>PASS</u>
LICENSE PLATE LAMPS PASS	🔳 📗 н	EATER AND DEFROSTER <u>PASS</u>
EMERGENCY FLASHERS PASS	В В	RAKE PAD MEASUREMENTS <u>PASS</u>
UNDER HOOD	L	= <u>10</u>
BLOCK TEST PASS		F <u>10</u>
OIL CHANGE PASS		₹ <u>10</u>
STEERING LINKS PASS	R	R <u>10</u>
FILLID AT LEVELO BASS		



# Additional Service Recommendations

safety and reliability, your technician Matt F made the following observations and recommends that you do the necessary repairs to resolve these issues.

In the process of inspecting your vehicle for

Red: requires immediate attention.

Yellow: in need of attention soon.

# Diagnostic: Airbag light is on.

## Item Description

Diagnostics when referred to in an automotive sense is the various testing done on the automobile to ensure safety and proper engine functioning. These tests are done with different sensors, computers and machines to establish a "cause and effect" relationship between what is working and what is not working with the automobile. The forms of diagnostics can range from brakes, to air conditioning, to suspension and many more.

#### Reason

Diagnostic work is often needed in order to fully examine the vehicle in order to understand what is needed to fix a specific problem. Over the years, the technological advances associated with automobile diagnostics have saved technicians countless hours of inch by inch vehicle inspection that can now be done through the work of various computers. Diagnostics is a crucial step in the repair of any vehicle.

Diagnostic: Thumping noise/looseness in steering when changing directions, esp. at the 12 o' Clock position. Could be faulty steering shaft assembly and/or steering rack.

# **Item Description**

Diagnostics when referred to in an automotive sense is the various testing done on the automobile to ensure safety and proper engine functioning. These tests are done with different sensors,





computers and machines to establish a "cause and effect" relationship between what is working and what is not working with the automobile. The forms of diagnostics can range from brakes, to air conditioning, to suspension and many more.

### Reason

Diagnostic work is often needed in order to fully examine the vehicle in order to understand what is needed to fix a specific problem. Over the years, the technological advances associated with automobile diagnostics have saved technicians countless hours of inch by inch vehicle inspection that can now be done through the work of various computers. Diagnostics is a crucial step in the repair of any vehicle.

Diagnostic: Right rear power window will go down but not up from master switch. Works normally at door switch. Most likely faulty master switch.

# **Item Description**

Diagnostics when referred to in an automotive sense is the various testing done on the automobile to ensure safety and proper engine functioning. These tests are done with different sensors, computers and machines to establish a "cause and effect" relationship between what is working and what is not working with the automobile. The forms of diagnostics can range from brakes, to air conditioning, to suspension and many more.

### Reason

Diagnostic work is often needed in order to fully examine the vehicle in order to understand what is needed to fix a specific problem. Over the years, the technological advances associated with automobile diagnostics have saved technicians countless hours of inch by inch vehicle inspection that can now be done through the work of various computers. Diagnostics is a crucial step in the repair of any vehicle.



# Sway Bar Links - Front: Rattling type

# noise from front when going over rough road. Start with sway bar links - boots torn and sockets dry.

## Item Description

A sway bar or stabilizer bar is a torsion spring that resists body roll motions. It is usually constructed out of a U-shaped steel bar that connects to the body at two points, and at the left and right sides of the suspension. If the left and right wheels move together, the bar rotates about its mounting points. If the wheels move relative to each other, the bar is subjected to torsion and forced to twist. Sway Bar Links are the connecting points of the sway bar to the chassis

### Reason

If the Sway Bar Links are found to be damaged or broken the sway bars effectiveness is reduced or eliminated, resulting in a "loose" feeling in the front end of the vehicle. Potential problems include abnormal tire wear and extra stress to various other suspension components.

# Cabin Air Filter Replacement

## Item Description

Prevents dirt, pollen, and other debris from entering the passenger compartment through the climate control system.

#### Reason

If not replaced, the air conditioning system will develop an odd odor. The air conditioning filter, also known as the cabin filter, removes dust and pollen from entering the car cabin.

# Bulb - Side Marker Replacement: Both front.

## Item Description

A low-intensity lamp mounted on the side of a vehicle to indicate its presence when seen from the side.





Cabin Air Filter

#### Reason

An important added safety feature.





Side Marker Light

# **Bulb - License Plate Light: Left**

# Item Description

The lights for illuminating the license plate on the back and/or front of a vehicle.

### Reason

If not replaced, you will fail the vehicle inspection and could receive a ticket for improper equipment.



License Plate Light

# \*Tire Balance and Rotate: Front 7/32, Rear 9/32

## **Item Description**

Balancing the vehicles tires are necessary to make sure the proper weight of the vehicle is distributed to the proper tire. Tire rotation helps protect tires against uneven wear by moving the tire location on the vehicle. Most tires will exhibit some form of wear based on numerous factors including: wheel alignment, miles driven, driving style and habits, and tire location on the vehicle. By moving or "rotating" the tires as recommended by the vehicle manufacturer, tires may wear more evenly; helping extend the life of the tires.



If not properly balanced, a vehicle's tires can experience abnormal wear which can significantly decrease the life of the tire. If not done, you will experience vibration in the steering wheel at certain highway speeds. Also, vibration will occur in the seat or floorboard at certain highway speeds. Tire



# Brake Job - Front (Replace Pads and Rotors): 1mm, Rotors severely rusted, noisy when applied.

## **Item Description**

Brake pads are the parts of a car's braking system that actually take the brunt of the frictional force necessary to stop the car. In a disc brake system, the brake pedal activates a hydraulic line which squeezes calipers against the rotors of the car's tires. Brake pads are positioned between the calipers and the rotors to absorb the energy and heat, and then provide enough grip to stop the car. Brake rotors are the parts within the wheels of an automobile which brake pads squeeze in order to slow the rotation of the wheel and bring the vehicle to a stop.

### Reason

Brake pads must be replaced before the friction material is worn away completely. When replacing the brake pads it is best to replace the rotors as well. This will allow the braking system to work at its highest level of performance, and will also allow the new pads to have the longest life possible.

# Brake Job - Rear (Replace Pads and Rotors): 2mm, Rotors severely rusted, noisy when applied.

# Item Description

Brake pads are the parts of a car's braking system that actually take the brunt of the frictional force necessary to stop the car. In a disc brake system, the brake pedal activates a hydraulic line which squeezes calipers against the rotors of the car's tires. Brake pads are positioned between the calipers and the rotors to absorb the energy and heat, and then provide enough grip to stop the car. Brake rotors are the parts within the wheels of an automobile which brake pads squeeze in order to slow the rotation of the wheel and bring the vehicle to a stop.



Pads&Rotors



#### Reason


Brake pads must be replaced before the friction material is worn away completely. When replacing the brake pads it is best to replace the rotors as well. This will allow the braking system to work at its highest level of performance, and will also allow the new pads to have the longest life possible.

# [Other]: need to replace driver side master switch

# **Item Description**

Speak with your service advisor for more information on this recommended service.

### Reason



# **Item Description**

On a vehicle with rack and pinion style steering, there is an inner tie rod end at each end of the steering rack. When the driver turns the steering wheel, the steering rack either pushes or pulls the front wheels. The inner tie rod end provides pivot points for the steering gear and transfers the movements of the steering wheel to the wheels.

#### Reason

If not replaced, faulty tie rod ends can cause the vehicle to pull to one side when driving or braking. Faulty tie rod ends can also cause uneven inner and outer tire wear. Bad tie rod ends can produce a "knocking" sound coming from the wheels when turning them back and forth while parking.

# Cooling Fan Assembly Replacement: need to replace cooling fan relay

# Item Description

The fan lowers the temperature of the engine. The cooling fan motor is an electric motor that turns the fan blades. When the vehicle is in traffic or under





Inner Tie Rod End

heavy load, the engine relies on the fan to cool itself. Some vehicles may use multiple electric fans for better control of the cooling system. For the most part, electric cooling fans are controlled by the same computer that controls the engine. However, in some engines, the fans are turned on and off by a temperature-sensitive switch mounted in either the radiator or elsewhere in the cooling system. The cooling fan assembly is attached to the radiator.

#### Reason

If not replaced, a failed cooling fan motor usually causes overheating. A fan that runs constantly can cause poor fuel economy, unwanted noise, and may completely discharge the battery.



Cooling Fan Assembly

PAD KIT, DISC BRAKE

SERVICE ADVISOR James Cook jrocktundra@gmail.com (785) 539-7441

PRINTED - 2/9/2024 QUOTE EXPIRES - 3/10/2024 REPAIR FACILITY ID - 2015 TOYOTA PRIUS JTDKN3DUXF0466925 Mileage 144,788

\$105.95

Parts and labor sub total \$516.87

\$105.95

PREPARED FOR INVENTORY: R53737C

SERVICE N	NAME		cos
Diagnost	tic: Airbag light is on. (I)		
LABOR	1.00 hours at \$165.00 per hour		\$165.0
	tic: Thumping noise/looseness in steering when ch y and/or steering rack. (I)	hanging directions, esp. at the 12 o' Clock position. Could be faulty steering sha	ft
LABOR	1.00 hours at \$165.00 per hour		\$165.0
Diagnosti switch. (I		up from master switch. Works normally at door switch. Most likely faulty master	
LABOR	1.00 hours at \$165.00 per hour		\$165.0
Sway Bar	r Links - Front: Rattling type noise from front when	n going over rough road. Start with sway bar links - boots torn and sockets dry.	(1)
LABOR	0.60 hours at \$165.00 per hour		\$99.0
PARTS	Qty Description	Number Price	Tota
	1 STABIZER LINK	644-233795 \$65.43	\$65.4
		Parts and labor sub total	\$164.4
Cabin Air	r Filter Replacement (I)		
LABOR	0.20 hours at \$59.85 per hour		\$11.9
PARTS	Qty Description	Number Price	Tot
	1 ELEMENT, AIR REFINER	87139YZZ82 \$27.98	\$27.9
		Parts and labor sub total	\$39.9
	de Marker Replacement: Both front. (I)		
LABOR	0.50 hours at \$165.00 per hour		
	0.50 hours at \$165.00 per hour  Oty Description	Number Price	Tota
LABOR	0.50 hours at \$165.00 per hour	Number         Price           CQ2825         \$1.21	Tota
LABOR	0.50 hours at \$165.00 per hour  Oty Description		Tot:
PARTS	0.50 hours at \$165.00 per hour  Oty Description	CQ2825 \$1.21	Tot:
PARTS	0.50 hours at \$165.00 per hour  Oty Description  2 2825 BULB	CQ2825 \$1.21	\$2.4 \$84.9
LABOR PARTS Bulb - Lice	0.50 hours at \$165.00 per hour  Qty Description 2 2825 BULB  cense Plate Light: Left (I)	CQ2825 \$1.21	Tot: \$2.4 \$84.9 \$49.5
LABOR PARTS Bulb - Lic	0.50 hours at \$165.00 per hour  Qty Description 2 2825 BULB  cense Plate Light: Left (I) 0.30 hours at \$165.00 per hour	CQ2825 \$1.21  Parts and labor sub total	\$2.4 \$84.9 \$49.5
LABOR PARTS Bulb - Lic	0.50 hours at \$165.00 per hour  Oty Description  2 2825 BULB  Cense Plate Light: Left (I)  0.30 hours at \$165.00 per hour  Oty Description	CQ2825 \$1.21  Parts and liabor sub total  Number Price	\$2.4 \$84.9 \$49.5 Total
PARTS  Bulb - Lic  LABOR  PARTS	0.50 hours at \$165.00 per hour  Oty Description  2 2825 BULB  Cense Plate Light: Left (I)  0.30 hours at \$165.00 per hour  Oty Description	CQ2825         \$1.21           Parts and labor sub total           Number         Price           CQ2825         \$1.21	\$2.4 \$84.9 \$49.5 Tota \$1.2
LABOR PARTS Bulb - Lic LABOR PARTS	0.50 hours at \$165.00 per hour    Qty   Description     2   2825 BULB	CQ2825         \$1.21           Parts and labor sub total           Number         Price           CQ2825         \$1.21	Total \$2.4 \$84.9 \$49.5 Total \$1.2 \$50.7
LABOR PARTS  Bulb - Lic LABOR PARTS  *Tire Bala	0.50 hours at \$165.00 per hour    Qty   Description     2   2825 BULB	CQ2825         \$1.21           Parts and labor sub total           Number         Price           CQ2825         \$1.21	\$49.5 Tota \$1.2
LABOR PARTS  Bulb - Lic LABOR PARTS  *Tire Bala LABOR	0.50 hours at \$165.00 per hour    Qty   Description     2   2825 BULB	CQ2825         \$1.21           Parts and labor sub total           Number         Price           CQ2825         \$1.21	Tot: \$2.4 \$84.9 \$49.5 Tot: \$1.2 \$50.7
Bulb - Lic LABOR PARTS  *Tire Bala LABOR PARTS	0.50 hours at \$165.00 per hour    Qty   Description     2   2825 BULB	CQ2825 \$1.21  Parts and labor sub total  Number Price CQ2825 \$1.21  Parts and labor sub total	Tot: \$2.4 \$84.9 \$49.5 Tot: \$1.2 \$50.7
Bulb - Lic LABOR PARTS  *Tire Bala LABOR PARTS	O.50 hours at \$165.00 per hour  Oty Description  2 2825 BULB  Cense Plate Light: Left (I)  O.30 hours at \$165.00 per hour  Oty Description  1 2825 BULB  ance and Rotate: Front 7/32, Rear 9/32 (I)	CQ2825 \$1.21  Parts and labor sub total  Number Price CQ2825 \$1.21  Parts and labor sub total	Total \$2.4 \$84.9 \$49.5 Total \$1.2 \$50.7 \$49.9 \$0.0
Bulb - Lic LABOR PARTS  *Tire Bala LABOR PARTS  Brake Join	Oty Description  2 2825 BULB  cense Plate Light: Left (I)  O.30 hours at \$165.00 per hour  Qty Description  1 2825 BULB  ance and Rotate: Front 7/32, Rear 9/32 (I)	CQ2825 \$1.21  Parts and labor sub total  Number Price CQ2825 \$1.21  Parts and labor sub total	Total \$2.4 \$49.5 Total \$1.2 \$50.7 \$49.9

0446547070

LABOR	1.50 hou	rs at \$165.00 per hour			\$247.5
PARTS	Qty	Description	Number	Price	Tot
	2	DISC, RR	4243112310	\$85.91	\$171.8
	1	PAD KIT, DISC BRAKE	0446647101	\$105.95	\$105.9
				Parts and labor sub total	\$525.2
[Other]: n	eed to rep	lace driver side master switch (I)			
LABOR	0.50 hou	rs at \$165.00 per hour			\$82.5
PARTS	Qty	Description	Number	Price	Tot
		MARTED CWITCH ACCV	8404060160	\$413.35	¢440.5
	1	MASTER SWITCH ASSY,	8404000100	\$413.33	\$413.5
	1	MASTER SWITCH ASSY,	0404000100	Parts and labor sub total	
Inner Tie				*******	
	Rod End R	Replacement: need to replace both inner tie ro		*******	\$495.8
LABOR	Rod End R			*******	\$413.3 \$495.8 \$297.0
LABOR	Rod End R	Replacement: need to replace both inner tie ro	ds both are loose (I)	Parts and labor sub total	\$495.8 \$297.0 Tota
Inner Tie LABOR PARTS	Rod End R	Replacement: need to replace both inner tie ro rs at \$165.00 per hour Description	ds both are loose (I)  Number	Parts and labor sub total  Price	\$495.8 \$297.0
LABOR PARTS	Rod End F 1.80 hou Qty 2	Replacement: need to replace both inner tie ro rs at \$165.00 per hour Description	Number 1017866	Parts and labor sub total  Price \$103.98	\$495.8 \$297.0 Tota \$207.9
PARTS	Rod End F  1.80 hou  Qty  2	Replacement: need to replace both inner tie ro rs at \$165.00 per hour Description inner tie rod AZ	Number 1017866	Parts and labor sub total  Price \$103.98	\$495.8 \$297.0 Tot: \$207.9
PARTS Cooling F	Rod End F  1.80 hou  Qty  2	Replacement: need to replace both inner tie ro rs at \$165.00 per hour  Description  inner tie rod AZ  bly Replacement: need to replace cooling fan	Number 1017866	Parts and labor sub total  Price \$103.98	\$495.8 \$297.0 Tot \$207.9 \$504.9

\$3,358.46
\$3.11
\$34.00
\$3,321.35
\$1,576.43
\$1,744.92



Little Apple Cars 2828 Amherst Ave Manhattan , KS 66502

(785) 539-7441