





Little Apple Cars



Automobile Status Report

Prepared For

INVENTORY: P7968



2013 Toyota COROLLA

Date March 26, 2024

VIN 2T1BU4EE0DC094711

Mileage 254966

RO# 6072457

Service Advisor

James Cook jrocktundra@gmail.com



Little Apple Cars Service Commitment

Excellence at every turn... and every straightaway

Our dealership's primary goal is to satisfy every customer at every opportunity. You visit our service department regularly, and we have developed a number of ways to make your visit more comfortable and informative. We know that you want straight answers, and that's the only way we will deliver it to you.

We understand that your knowledge of your vehicle and its necessary repairs is probably not on par with the understanding that your technician has. In order to be sure that his findings and reporting is as clear and concise as possible, we use this Vehicle Information Booklet as a tool to help us communicate your vehicle's condition to you.

Our technicians are the most qualified to work on your vehicle. They have trained extensively, and partake in continuing education regularly to be sure that they are up to date on any changes and improvements handed down from the manufacturer. Our service advisors strive to make your experience with us a pleasant one. They are here to attend to your automotive needs as well as communicate effectively with your technician and you.

Please make yourself comfortable in our waiting area. Watch some TV, use your laptop with our free WI-FI access or just relax and enjoy the quiet. Our courtesy shuttle can take you shopping, to a movie or home if you prefer.

We appreciate your business and will continue to strive for excellence in everything we do for you.

Multi-Point Inspection Form

RO# 6072457 INVENTORY: P7968

VIN 2T1BU4EE0DC094711

Advisor James Cook Technician Matt Fisher Created On 3/26/2024

Checked and OK at this time	May Require Future Attention	n Requires immediate attention
ROAD TEST		FUNCTIONAL
BRAKE OPERATION PASS	I ■ H	HORN <u>PASS</u>
ENGINE OPERATION PASS		TRES <u>PASS</u>
DRIVETRAIN OPERATION PASS		F <u>10</u>
TRANSMISSION OPERATION PASS	R R	RF <u>10</u>
LIGHTS		R <u>6</u>
TAIL LAMPS PASS	R	RR <u>7</u>
HEAD LAMPS PASS		SEAT BELTS <u>PASS</u>
STOP LAMPS PASS		WINDSHIELD <u>PASS</u>
TURN SIGNALS PASS	P	PARKING BRAKE <u>PASS</u>
SIDE MARKER LAMPS PASS		WIPERS AND WASHERS <u>PASS</u>
LICENSE PLATE LAMPS PASS		HEATER AND DEFROSTER <u>PASS</u>
EMERGENCY FLASHERS PASS		BRAKE PAD MEASUREMENTS <u>PASS</u>
UNDER HOOD		.F <u>7</u>
BLOCK TEST PASS		RF <u>7</u>
OIL CHANGE PASS		_R <u>4, Drum</u>
STEERING LINKS PASS		RR <u>4. Drum</u>
FLUID AT LEVELS PASS		

Additional Service Recommendations

Red: requires immediate attention.

In the process of inspecting your vehicle for safety and reliability, your technician **Matt F** made the following observations and recommends that you do the necessary repairs to resolve these issues.

Yellow: in need of attention soon.

Windshield Replacement: Cracked

Item Description

The windshield of a vehicle is a transparent screen of glass put in place to protect the occupants in the vehicle. The vehicle's windshield protects the inside of the vehicle from the outside elements, as well as promoting the structural integrity of the vehicle.

Reason

If not replaced, a damaged windshield not only puts the driver and passengers at risk but also the other vehicles on the road if the windshield breaks completely.



Windshield

Cabin Air Filter Replacement

Item Description

Prevents dirt, pollen, and other debris from entering the passenger compartment through the climate control system.

Reason

If not replaced, the air conditioning system will develop an odd odor. The air conditioning filter, also known as the cabin filter, removes dust and pollen from entering the car cabin.



Cabin Air Filter

Engine Air Filter Replacement

Item Description

The air filter prevents dirt and debris from entering the engine, which could otherwise cause premature engine wear.

Reason

If not replaced, poor gas mileage and premature



Air Filter

[Other]: Driver's door check strap is broken allowing door to open too far and hit stops in hinges.

Item Description

Speak with your service advisor for more information on this recommended service.

Reason

Bulb - License Plate Light: Both

Item Description

The lights for illuminating the license plate on the back and/or front of a vehicle.

Reason

If not replaced, you will fail the vehicle inspection and could receive a ticket for improper equipment.



License Plate Light

Bulb - Side Marker Replacement: Both front

Item Description

A low-intensity lamp mounted on the side of a vehicle to indicate its presence when seen from the side.





Reason

Side Marker Light

*Tires - 2: 205/55R16 - Rear tires 3/32

Item Description

A tire is a round component made of rubber and reinforced with chords or belts made of several choices of materials. The tire is filled with air or nitrogen and surrounds a wheel's rim to transfer a vehicle's load from the axle through the wheel to the ground and to provide traction on the road's surface. With only four small contact patches between you and the road you want them to be as good as they can possibly be.

Reason

According to most states' laws, tires are legally worn out when they have worn down to 2/32" of remaining tread depth. As a tire wears it's important to realize that the tire's ability to perform in rain and snow will be reduced. With 2/32" of remaining tread depth, resistance to hydroplaning in the rain at highway speeds has been significantly reduced, and traction in snow has been virtually eliminated. If rain and wet roads are a concern, you should consider replacing your tires when they reach approximately 4/32" of remaining tread depth.

If snow-covered roads are a concern, you should consider replacing your tires when they reach approximately 6/32" of remaining tread depth to maintain good mobility. Because tread depth is such an important element for snow traction, winter tires usually start with noticeably deeper tread depths than typical All-Season or summer tires. Some winter tires even have a second series of "wear bars" molded in their tread pattern indicating approximately 6/32" remaining tread depth to warn you when your tires no longer meet the desired tread depth.

*Tire Balance and Rotate: Balance front tires and move to rear. Place new tires on front.

Item Description



Tires

Balancing the vehicles tires are necessary to make sure the proper weight of the vehicle is distributed to the proper tire. Tire rotation helps protect tires against uneven wear by moving the tire location on the vehicle. Most tires will exhibit some form of wear based on numerous factors including: wheel alignment, miles driven, driving style and habits, and tire location on the vehicle. By moving or "rotating" the tires as recommended by the vehicle manufacturer, tires may wear more evenly; helping extend the life of the tires.

Reason

If not properly balanced, a vehicle's tires can experience abnormal wear which can significantly decrease the life of the tire. If not done, you will experience vibration in the steering wheel at certain highway speeds. Also, vibration will occur in the seat or floorboard at certain highway speeds. Tire wear will become scalloped or cupped.



SERVICE ADVISOR James Cook jrocktundra@gmail.com (785) 539-7441

PRINTED - 3/26/2024 QUOTE EXPIRES - 4/25/2024 REPAIR FACILITY ID - 2013 TOYOTA COROLLA 2T1BU4EE0DC094711 Mileage 254,966

PREPARED FOR INVENTORY: P7968

SERVICE N	NAME			•	cos
Windshie	ld Replacem	ent: Cracked (I)			
LABOR	0.10 hours	at \$3,200.00 per hour		\$3	320.0
Cabin Air	Filter Repla	cement (I)			
LABOR		at \$130.00 per hour		s	\$39.0
PARTS	Qty	Description	Number	Price	Tota
	1	ELEMENT, AIR REFINER	87139YZZ82		\$27.9
	· · · · · ·				\$66.9
Engine A	in Ellton Donle	accompant (I)			
	ir Filter Repla	• •			
LABOR		at \$60.00 per hour	*****		\$6.00
PARTS	Qty	Description 51 SMCNT CUID ACCOUNTS	Number	Price	Tota
	1	ELEMENT SUB-ASSY, AI	17801YZZ05	\$29.99 \$	\$29.99
				Parts and labor sub total \$	\$35.99
[Other]: [Driver's door	check strap is broken allowing door to open	too far and hit stops in hinges. (I)		
LABOR		at \$165.00 per hour		¢ 1	132.00
PARTS	Qty	Description	Number	Price	Tota
PARTS	1	CHECK ASSY, FR DOOR	6861002160		112.3
		CHECK ASST, FR DOOR	0001002100	\$11Z.33 \$1	112.5
	<u> </u>				
				Parts and labor sub total \$2	244.33
Bulb - Lic		.ight: Both (I)		Parts and labor sub total \$2	244.33
	cense Plate L	Light: Both (I)			
LABOR	cense Plate L	at \$165.00 per hour	Number	s	\$66.00
	cense Plate L 0.40 hours	at \$165.00 per hour Description	Number 9913212050	\$ Price	\$66.00 Tota
LABOR	cense Plate L	at \$165.00 per hour	Number 9913212050	Price \$4.17	\$66.00 Tota \$8.34
LABOR	cense Plate L 0.40 hours	at \$165.00 per hour Description		Price \$4.17	\$66.00 Tota \$8.34
PARTS	0.40 hours : Qty 2	at \$165.00 per hour Description		Price \$4.17	\$66.00 Tota \$8.34
LABOR PARTS Bulb - Sid	0.40 hours : Qty 2	at \$165.00 per hour Description BULB eplacement: Both front (I)		Price \$4.17 Parts and labor sub total \$	\$66.00 Tota \$8.34 \$74.34
LABOR PARTS Bulb - Sic	Oty 2 de Marker Re 0.30 hours	at \$165.00 per hour Description BULB eplacement: Both front (I) at \$165.00 per hour	9913212050	Price \$4.17 Parts and labor sub total \$	\$66.00 Tota \$8.34 \$74.34
LABOR PARTS Bulb - Sic	0.40 hours : Qty 2	at \$165.00 per hour Description BULB eplacement: Both front (I)		Price \$4.17 Parts and liabor sub total \$ Price	\$66.00 Tota \$8.34 \$74.34 \$49.50
PARTS	O.40 hours : Oty 2 de Marker Re 0.30 hours : Oty	at \$165.00 per hour Description BULB eplacement: Both front (I) at \$165.00 per hour Description	9913212050 Number	Price \$4.17 Parts and liabor sub total \$ Price	\$66.00 Tota \$8.34 \$74.34 \$49.50 Tota \$19.99
LABOR PARTS Bulb - Sic LABOR PARTS	O.40 hours and O.40 h	at \$165.00 per hour Description BULB Eplacement: Both front (I) at \$165.00 per hour Description MARKER BULB	9913212050 Number	Price \$4.17 Parts and labor sub total \$ Price \$19.99 \$	\$66.00 Tota \$8.34 \$74.34 \$49.50 Tota \$19.99
LABOR PARTS Bulb - Sic LABOR PARTS *Tires - 2:	cense Plate L 0.40 hours : Oty 2 de Marker Re 0.30 hours : Oty 1	at \$165.00 per hour Description BULB Eplacement: Both front (I) at \$165.00 per hour Description MARKER BULB - Rear tires 3/32 (I)	9913212050 Number	Price \$4.17 Parts and labor sub total \$ Price \$19.99 \$	\$66.00 Total \$8.34 \$74.34 \$49.50 Total \$19.99 \$69.49
LABOR PARTS Bulb - Sic LABOR PARTS *Tires - 2: LABOR	0.40 hours : Oty 2 de Marker Re 0.30 hours : Oty 1 : 205/55R16 - 0.60 hours :	at \$165.00 per hour Description BULB Eplacement: Both front (I) at \$165.00 per hour Description MARKER BULB - Rear tires 3/32 (I) at \$165.00 per hour	9913212050 Number 168STBP2	Price \$4.17 Parts and labor sub total \$ Price \$19.99 \$ Parts and labor sub total \$	\$66.00 Total \$8.34 \$74.34 \$49.50 Total \$19.99 \$69.49
LABOR PARTS Bulb - Sic LABOR PARTS *Tires - 2: LABOR	de Marker Re 0.30 hours a Qty 1 2 2205/55R16 - 0.60 hours a	at \$165.00 per hour Description BULB Eplacement: Both front (I) at \$165.00 per hour Description MARKER BULB - Rear tires 3/32 (I) at \$165.00 per hour Description	9913212050 Number 168STBP2 Number	Price \$4.17 Parts and labor sub total \$ Price \$19.99 \$ Parts and labor sub total \$ Price	Total \$8.349.50 Total \$8.39.90 Total \$19.90 Total Total Total Total
LABOR PARTS Bulb - Sic LABOR PARTS *Tires - 2: LABOR	0.40 hours : Oty 2 de Marker Re 0.30 hours : Oty 1 : 205/55R16 - 0.60 hours :	at \$165.00 per hour Description BULB Eplacement: Both front (I) at \$165.00 per hour Description MARKER BULB - Rear tires 3/32 (I) at \$165.00 per hour	9913212050 Number 168STBP2	Price \$4.17 Parts and labor sub total \$ Price \$19.99 \$ Parts and labor sub total \$ Price \$75.56 \$1	\$66.00 Total \$8.30 \$74.30 \$49.51 Total \$19.90 \$99.00 Total
LABOR PARTS Bulb - Sic LABOR PARTS *Tires - 2: LABOR PARTS	2 0.40 hours : Qty 2 de Marker Re 0.30 hours : Qty 1 2 205/55R16 - 0.60 hours : Qty 2	at \$165.00 per hour Description BULB Eplacement: Both front (I) at \$165.00 per hour Description MARKER BULB - Rear tires 3/32 (I) at \$165.00 per hour Description TIRE 205/55R16	9913212050 Number 168STBP2 Number 42751ADV557	Price \$4.17 Parts and labor sub total \$ Price \$19.99 \$ Parts and labor sub total \$ Price	\$66.00 Total \$8.30 \$74.30 \$49.51 Total \$19.90 \$99.00 Total
LABOR PARTS Bulb - Sic LABOR PARTS *Tires - 2: LABOR PARTS	2 0.40 hours : Qty 2 de Marker Re 0.30 hours : Qty 1 2 205/55R16 - 0.60 hours : Qty 2	at \$165.00 per hour Description BULB Eplacement: Both front (I) at \$165.00 per hour Description MARKER BULB - Rear tires 3/32 (I) at \$165.00 per hour Description	9913212050 Number 168STBP2 Number 42751ADV557	Price \$4.17 Parts and labor sub total \$ Price \$19.99 \$ Parts and labor sub total \$ Price \$75.56 \$1	\$66.00 Tota \$8.34 \$74.34 \$49.50 Tota \$19.99 \$69.45 \$99.00 Tota 151.12
LABOR PARTS Bulb - Sic LABOR PARTS *Tires - 2: LABOR PARTS	2 0.40 hours : Qty 2 de Marker Re 0.30 hours : Qty 1 2 205/55R16 - 0.60 hours : Qty 2	at \$165.00 per hour Description BULB Eplacement: Both front (I) at \$165.00 per hour Description MARKER BULB - Rear tires 3/32 (I) at \$165.00 per hour Description TIRE 205/55R16	9913212050 Number 168STBP2 Number 42751ADV557	Price \$4.17 Parts and labor sub total \$ Price \$19.99 \$ Parts and labor sub total \$ Price \$75.56 \$1 Parts and labor sub total \$2	Total \$8.34 \$49.50 Total \$19.99 \$69.49

Total	\$1.148.31
Taxes	\$3.11
Shop Charges	\$34.00
Subtotal	\$1,111.20
Total Parts	\$349.75
Total Labor	\$761.45



Little Apple Cars 2828 Amherst Ave Manhattan , KS 66502

(785) 539-7441