



Little Apple Cars



Automobile Status Report

Prepared For

INVENTORY: P66335A



2012 Jeep WRANGLER

Date February 28, 2024

VIN 1C4AJWBG5CL266860

Mileage 129482

RO# 6071063

Service Advisor

James Cook

jrocktundra@gmail.com



Little Apple Cars
2828 Amherst Ave
Manhattan, KS 66502

Little Apple Cars Service Commitment

Excellence at every turn... and every straightaway

Our dealership's primary goal is to satisfy every customer at every opportunity. You visit our service department regularly, and we have developed a number of ways to make your visit more comfortable and informative. We know that you want straight answers, and that's the only way we will deliver it to you.

We understand that your knowledge of your vehicle and its necessary repairs is probably not on par with the understanding that your technician has. In order to be sure that his findings and reporting is as clear and concise as possible, we use this Vehicle Information Booklet as a tool to help us communicate your vehicle's condition to you.

Our technicians are the most qualified to work on your vehicle. They have trained extensively, and partake in continuing education regularly to be sure that they are up to date on any changes and improvements handed down from the manufacturer. Our service advisors strive to make your experience with us a pleasant one. They are here to attend to your automotive needs as well as communicate effectively with your technician and you.

Please make yourself comfortable in our waiting area. Watch some TV, use your laptop with our free WI-FI access or just relax and enjoy the quiet. Our courtesy shuttle can take you shopping, to a movie or home if you prefer.

We appreciate your business and will continue to strive for excellence in everything we do for you.

Multi-Point Inspection Form

RO# 6071063

INVENTORY: P66335A

VIN 1C4AJWBG5CL266860

Advisor James Cook

Technician Noah Simmons

Created On 2/28/2024



Checked and OK at this time



May Require Future Attention



Requires immediate attention

ROAD TEST

			BRAKE OPERATION <u>PASS</u>
			ENGINE OPERATION <u>PASS</u>
			DRIVETRAIN OPERATION <u>PASS</u>
			TRANSMISSION OPERATION <u>PASS</u>

LIGHTS

			TAIL LAMPS <u>PASS</u>
			HEAD LAMPS <u>PASS</u>
			STOP LAMPS <u>PASS</u>
			TURN SIGNALS <u>PASS</u>
			SIDE MARKER LAMPS <u>PASS</u>
			LICENSE PLATE LAMPS <u>PASS</u>
			EMERGENCY FLASHERS <u>PASS</u>

UNDER HOOD

			BLOCK TEST <u>PASS</u>
			OIL CHANGE <u>PASS</u>
			STEERING LINKS <u>PASS</u>
			FLUID AT LEVELS <u>PASS</u>

FUNCTIONAL

			HORN <u>PASS</u>
			TIRES <u>PASS</u>
			LF <u>19</u>
			RF <u>19</u>
			LR <u>19</u>
			RR <u>19</u>
			SEAT BELTS <u>PASS</u>
			WINDSHIELD <u>PASS</u>
			PARKING BRAKE <u>PASS</u>
			WIPERS AND WASHERS <u>PASS</u>
			HEATER AND DEFROSTER <u>PASS</u>
			BRAKE PAD MEASUREMENTS <u>PASS</u>
			LF <u>8</u>
			RF <u>8</u>
			LR <u>8</u>
			RR <u>8</u>

Additional Service Recommendations

In the process of inspecting your vehicle for safety and reliability, your technician **Noah S** made the following observations and recommends that you do the necessary repairs to resolve these issues.

■ Red: requires immediate attention.

■ Yellow: in need of attention soon.

Windshield Replacement: Cracked

Item Description

The windshield of a vehicle is a transparent screen of glass put in place to protect the occupants in the vehicle. The vehicle's windshield protects the inside of the vehicle from the outside elements, as well as promoting the structural integrity of the vehicle.

Reason

If not replaced, a damaged windshield not only puts the driver and passengers at risk but also the other vehicles on the road if the windshield breaks completely.



Windshield

[Other]: Engine oil filter housing assembly with sensors and necessary gaskets. MIL is on with DTC P0522.

Item Description

Speak with your service advisor for more information on this recommended service.

Reason



[Other]: Has aftermarket "Cold Air" style engine air filter - needs serviced.

Item Description

Speak with your service advisor for more information on this recommended service.

Reason



Bulb - Side Marker Replacement: Both front side marker lights out.

Item Description

A low-intensity lamp mounted on the side of a vehicle to indicate its presence when seen from the side.

Reason

An important added safety feature.



Side Marker Light

Bulb - License Plate Light

Item Description

The lights for illuminating the license plate on the back and/or front of a vehicle.

Reason

If not replaced, you will fail the vehicle inspection and could receive a ticket for improper equipment.



License Plate Light

Lug and Wheel studs: One broken lug stud on right rear.

Item Description

These are the connectors that fasten the wheels to the vehicle. Over time, the lug and wheel studs can become worn down or even lost altogether.

Reason

If not replaced, this creates a serious hazard to the driver and passengers. Without the lug and wheel studs functioning properly, the wheel will not be properly secured to the vehicle. If not addressed, eventually the wheel can separate, causing serious damage to the vehicle.



Axle Seal: Both sides of rear axle leaking (dripping onto wheels).

Possible contamination of E-brake shoes - not holding completely.

Item Description

Axle seals are used to ensure proper seals for various parts of the vehicle's axles.

Reason

These seals must be maintained in order to ensure proper functionality of the vehicle's axles.



Thermostat Housing Replacement

Item Description

The thermostat is a device that measures the vehicle's internal temperature. The thermostat housing is the casing the thermostat is enclosed in.

Reason

If the thermostat housing becomes cracked or broken, it must be replaced in order to properly enclose the thermostat.



Thermostat Housing

COMPLETED REPAIRS

RO# 6071063 - 2/28/2024 10:27 AM

SERVICE ADVISOR

James Cook

jrocktundra@gmail.com

(785) 539-7441

PREPARED FOR

INVENTORY: P66335A

PRINTED - 2/28/2024
QUOTE EXPIRES - 3/29/2024
REPAIR FACILITY ID -

2012 JEEP WRANGLER

1C4AJWBG5CL266860

Mileage 129,482

SERVICE NAME					COST
Windshield Replacement: Cracked (I)					
LABOR	0.10 hours at \$3,100.00 per hour				\$310.00
[Other]: Engine oil filter housing assembly with sensors and necessary gaskets. MIL is on with DTC P0522. (I)					
LABOR	2.50 hours at \$165.00 per hour				\$412.50
PARTS	Qty	Description	Number	Price	Total
	1	OIL FILTER HOUSING	ROBBINS	\$448.87	\$448.87
	6	GASKET	ROBBINS	\$9.97	\$59.82
	6	GASKET	ROBBINS	\$22.05	\$132.30
				Parts and labor sub total	\$1,053.49
[Other]: Has aftermarket "Cold Air" style engine air filter - needs serviced. (I)					
LABOR	0.00 hours at \$0.00 per hour				\$0.00
Bulb - Side Marker Replacement: Both front side marker lights out. (I)					
LABOR	0.40 hours at \$165.00 per hour				\$66.00
PARTS	Qty	Description	Number	Price	Total
	2	BULB	CQ-168	\$1.73	\$3.46
				Parts and labor sub total	\$69.46
Bulb - License Plate Light (I)					
LABOR	0.30 hours at \$165.00 per hour				\$49.50
PARTS	Qty	Description	Number	Price	Total
	1	BULB	CQ-194	\$1.17	\$1.17
				Parts and labor sub total	\$50.67
Lug and Wheel studs: One broken lug stud on right rear. (I)					
LABOR	0.50 hours at \$165.00 per hour				\$82.50
PARTS	Qty	Description	Number	Price	Total
	1	LUG STUD	ROBBINS	\$28.94	\$28.94
				Parts and labor sub total	\$111.44
Axle Seal: Both sides of rear axle leaking (dripping onto wheels). Possible contamination of E-brake shoes - not holding completely. (I)					
LABOR	4.60 hours at \$165.00 per hour				\$759.00
PARTS	Qty	Description	Number	Price	Total
	2	AXLE SEAL	ROBBINS	\$63.59	\$127.18
	2	BEARING	ROBBINS	\$276.94	\$553.88
	2	RETAINER	ROBBINS	\$79.34	\$158.68
				Parts and labor sub total	\$1,598.74
Thermostat Housing Replacement (I)					
LABOR	1.00 hours at \$165.00 per hour				\$165.00
PARTS	Qty	Description	Number	Price	Total
	1	THERMOSTAT HOUSING	MCS82303	\$42.36	\$42.36
				Parts and labor sub total	\$207.36

Total Labor	\$1,844.50
Total Parts	\$1,556.66
Subtotal	\$3,401.16
Shop Charges	\$34.00
Taxes	\$3.11
Total	\$3,438.27



Little Apple Cars
 2828 Amherst Ave
 Manhattan , KS 66502

(785) 539-7441