





# Little Apple Cars Automobile Status Report

Prepared For

xtime

INVENTORY: P7875A

2013 Toyota PRIUS V Date March 13, 2024 VIN JTDZN3EU0D3265883 Mileage 83037 RO# 6071812

Service Advisor

James Cook jrocktundra@gmail.com



## Little Apple Cars Service Commitment

### Excellence at every turn... and every straightaway

Our dealership's primary goal is to satisfy every customer at every opportunity. You visit our service department regularly, and we have developed a number of ways to make your visit more comfortable and informative. We know that you want straight answers, and that's the only way we will deliver it to you.

We understand that your knowledge of your vehicle and its necessary repairs is probably not on par with the understanding that your technician has. In order to be sure that his findings and reporting is as clear and concise as possible, we use this Vehicle Information Booklet as a tool to help us communicate your vehicle's condition to you.

Our technicians are the most qualified to work on your vehicle. They have trained extensively, and partake in continuing education regularly to be sure that they are up to date on any changes and improvements handed down from the manufacturer. Our service advisors strive to make your experience with us a pleasant one. They are here to attend to your automotive needs as well as communicate effectively with your technician and you.

Please make yourself comfortable in our waiting area. Watch some TV, use your laptop with our free WI-FI access or just relax and enjoy the quiet. Our courtesy shuttle can take you shopping, to a movie or home if you prefer.

We appreciate your business and will continue to strive for excellence in everything we do for you.

### Multi-Point Inspection Form

RO# 6071812 INVENTORY: P7875A

VIN JTDZN3EU0D3265883

Advisor James Cook Technician Matt Fisher Created On 3/13/2024

Checked and OK at this time	May Require Future Attention	Requires immediate attention
ROAD TEST		FUNCTIONAL
BRAKE OPERATION PASS	HO	ORN <u>PASS</u>
ENGINE OPERATION PASS	TIF	RES <u>PASS</u>
DRIVETRAIN OPERATION PASS	LF	: <u>10</u>
TRANSMISSION OPERATION PASS	RF	= <u>10</u>
LIGHTS	LR	R <u>7</u>
TAIL LAMPS PASS	RR	R <u>Z</u>
HEAD LAMPS PASS	SE SE	EAT BELTS <u>PASS</u>
STOP LAMPS PASS	■	INDSHIELD <u>PASS</u>
TURN SIGNALS PASS	PA	ARKING BRAKE <u>PASS</u>
SIDE MARKER LAMPS PASS	■   w	IPERS AND WASHERS <u>PASS</u>
LICENSE PLATE LAMPS PASS	HE HE	EATER AND DEFROSTER <u>PASS</u>
EMERGENCY FLASHERS PASS	BF	RAKE PAD MEASUREMENTS <u>PASS</u>
UNDER HOOD	LF	: <u>6</u>
BLOCK TEST PASS	RF	<u> 6</u>
OIL CHANGE PASS	LR	₹ 6
STEERING LINKS PASS	RR	R <u>6</u>
STEERING LINKS (ASS)		

## Additional Service Recommendations

Red: requires immediate attention.

In the process of inspecting your vehicle for safety and reliability, your technician **Matt F** made the following observations and recommends that you do the necessary repairs to resolve these issues.

Yellow: in need of attention soon.

#### Cabin Air Filter Replacement

#### Item Description

Prevents dirt, pollen, and other debris from entering the passenger compartment through the climate control system.

#### Reason

If not replaced, the air conditioning system will develop an odd odor. The air conditioning filter, also known as the cabin filter, removes dust and pollen from entering the car cabin.



Cabin Air Filter

#### **Engine Air Filter Replacement**

#### Item Description

The air filter prevents dirt and debris from entering the engine, which could otherwise cause premature engine wear.

#### Reason

If not replaced, poor gas mileage and premature engine wear will result.



Air Filter

## \*Tires - 2: 205/60R16 - Front tires 3/32

#### **Item Description**

A tire is a round component made of rubber and reinforced with chords or belts made of several choices of materials. The tire is filled with air or nitrogen and surrounds a wheel's rim to transfer a vehicle's load from the axle through the wheel to the ground and to provide traction on the road's surface. With only four small contact patches between you and the road you want them to be as

good as they can possibly be.

#### Reason

According to most states' laws, tires are legally worn out when they have worn down to 2/32" of remaining tread depth. As a tire wears it's important to realize that the tire's ability to perform in rain and snow will be reduced. With 2/32" of remaining tread depth, resistance to hydroplaning in the rain at highway speeds has been significantly reduced, and traction in snow has been virtually eliminated. If rain and wet roads are a concern, you should consider replacing your tires when they reach approximately 4/32" of remaining tread depth.

If snow-covered roads are a concern, you should consider replacing your tires when they reach approximately 6/32" of remaining tread depth to maintain good mobility. Because tread depth is such an important element for snow traction, winter tires usually start with noticeably deeper tread depths than typical All-Season or summer tires. Some winter tires even have a second series of "wear bars" molded in their tread pattern indicating approximately 6/32" remaining tread depth to warn you when your tires no longer meet the desired tread depth.



Tires

SERVICE ADVISOR James Cook jrocktundra@gmail.com (785) 539-7441

PRINTED - 3/13/2024 QUOTE EXPIRES - 4/12/2024 REPAIR FACILITY ID - PREPARED FOR INVENTORY: P7875A

2013 TOYOTA PRIUS V JTDZN3EU0D3265883 Mileage 83,037

SERVICE N	IAME				cost
Cabin Air	Filter Rep	placement (I)			
LABOR	0.30 hou	rs at \$130.00 per hour			\$39.00
PARTS	Qty	Description	Number	Price	Total
	1	ELEMENT, AIR REFINER	87139YZZ82	\$27.98	\$27.98
				Parts and labor sub total	\$66.98
Engine Ai	ir Filter Re	eplacement (I)			
LABOR	0.10 hou	rs at \$60.00 per hour			\$6.00
PARTS	Qty	Description	Number	Price	Total
	1	ELEMENT SUB-ASSY, AI	17801YZZ12	\$29.99	\$29.99
				Parts and labor sub total	\$35.99
*Tires - 2:	205/60R1	6 - Front tires 3/32 (I)			
LABOR	0.60 hou	irs at \$137.50 per hour			\$82.50
PARTS	Qty	Description	Number	Price	Total
	2	TIRE 205/60R16	42751IRO7144	\$84.10	\$168.20
				Parts and labor sub total	\$250.70

Total	\$390.78
Taxes	\$3.11
Shop Charges	\$34.00
Subtotal	\$353.67
Total Parts	\$226.17
Total Labor	\$127.50



Little Apple Cars 2828 Amherst Ave Manhattan , KS 66502

(785) 539-7441