



Little Apple Cars



Automobile Status Report

Prepared For

INVENTORY: R555155A



2013 Nissan VERSA

Date March 28, 2024

VIN 3N1CN7APXDL847669

Mileage 123203

RO# 6072134

Service Advisor

James Cook

jrocktundra@gmail.com



Little Apple Cars
2828 Amherst Ave
Manhattan, KS 66502

Little Apple Cars Service Commitment

Excellence at every turn... and every straightaway

Our dealership's primary goal is to satisfy every customer at every opportunity. You visit our service department regularly, and we have developed a number of ways to make your visit more comfortable and informative. We know that you want straight answers, and that's the only way we will deliver it to you.

We understand that your knowledge of your vehicle and its necessary repairs is probably not on par with the understanding that your technician has. In order to be sure that his findings and reporting is as clear and concise as possible, we use this Vehicle Information Booklet as a tool to help us communicate your vehicle's condition to you.

Our technicians are the most qualified to work on your vehicle. They have trained extensively, and partake in continuing education regularly to be sure that they are up to date on any changes and improvements handed down from the manufacturer. Our service advisors strive to make your experience with us a pleasant one. They are here to attend to your automotive needs as well as communicate effectively with your technician and you.

Please make yourself comfortable in our waiting area. Watch some TV, use your laptop with our free WI-FI access or just relax and enjoy the quiet. Our courtesy shuttle can take you shopping, to a movie or home if you prefer.

We appreciate your business and will continue to strive for excellence in everything we do for you.

Multi-Point Inspection Form

RO# 6072134

INVENTORY: R555155A

VIN 3N1CN7APXDL847669

Advisor James Cook

Technician Randy Countryman

Created On 3/28/2024



Checked and OK at this time



May Require Future Attention



Requires immediate attention

ROAD TEST

<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	BRAKE OPERATION
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	ENGINE OPERATION
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	DRIVETRAIN OPERATION
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	TRANSMISSION OPERATION

LIGHTS

<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	TAIL LAMPS
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	HEAD LAMPS
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	STOP LAMPS
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	TURN SIGNALS
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	SIDE MARKER LAMPS
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	LICENSE PLATE LAMPS
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	EMERGENCY FLASHERS

UNDER HOOD

<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	BLOCK TEST
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	OIL CHANGE
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	STEERING LINKS
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	FLUID AT LEVELS

FUNCTIONAL

<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	HORN
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	TIRES
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	LF
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	RF
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	LR
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	RR
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	SEAT BELTS
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	WINDSHIELD
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	PARKING BRAKE
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	WIPERS AND WASHERS
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	HEATER AND DEFROSTER
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	BRAKE PAD MEASUREMENTS
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	LF
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	RF
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	LR
<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	RR

COMPLETED REPAIRS

RO# 6072134 - 3/28/2024 7:45 AM

SERVICE ADVISOR
James Cook
jrocktundra@gmail.com
(785) 539-7441

PREPARED FOR
INVENTORY: R555155A

PRINTED - 3/28/2024
QUOTE EXPIRES - 4/27/2024
REPAIR FACILITY ID -

2013 NISSAN VERSA
3N1CN7APXDL847669
Mileage 123,203

SERVICE NAME	COST
--------------	------

Total Labor	\$0.00
Total Parts	\$0.00
Subtotal	\$0.00
Shop Charges	\$0.00
Taxes	\$0.00
Total	\$0.00



Little Apple Cars
2828 Amherst Ave
Manhattan , KS 66502

(785) 539-7441