



Little Apple Cars



Automobile Status Report

Prepared For

INVENTORY: P7991



2023 Ford MUSTANG

Date April 03, 2024

VIN 1FA6P8TH2P5111111

Mileage 22907

RO# 6072926

Service Advisor

James Cook

jrocktundra@gmail.com



Little Apple Cars
2828 Amherst Ave
Manhattan, KS 66502

Little Apple Cars

Service Commitment

Excellence at every turn... and every straightaway

Our dealership's primary goal is to satisfy every customer at every opportunity. You visit our service department regularly, and we have developed a number of ways to make your visit more comfortable and informative. We know that you want straight answers, and that's the only way we will deliver it to you.

We understand that your knowledge of your vehicle and its necessary repairs is probably not on par with the understanding that your technician has. In order to be sure that his findings and reporting is as clear and concise as possible, we use this Vehicle Information Booklet as a tool to help us communicate your vehicle's condition to you.

Our technicians are the most qualified to work on your vehicle. They have trained extensively, and partake in continuing education regularly to be sure that they are up to date on any changes and improvements handed down from the manufacturer. Our service advisors strive to make your experience with us a pleasant one. They are here to attend to your automotive needs as well as communicate effectively with your technician and you.

Please make yourself comfortable in our waiting area. Watch some TV, use your laptop with our free WI-FI access or just relax and enjoy the quiet. Our courtesy shuttle can take you shopping, to a movie or home if you prefer.

We appreciate your business and will continue to strive for excellence in everything we do for you.

Multi-Point Inspection Checklist

RO# 6072926

Customer Name INVENTORY: P7991

Advisor Name James Cook

Technician Name Jaden Kennington

Created on 3/22/2024 1:17 PM

Printed on 4/3/2024

Did your Service Advisor review the results of this multi-point inspection checklist with you?

- Checked and OK at this time May Require Future Attention Requires immediate attention

Vehicle/Dealership Information

- Year/Make/Model 2023fordmustang
- Stock Number p7991
- Exterior Color white
- Interior Color black
- VIN 1FA6P8TH2P5111111
- Date Aquired 3/27/24
- Date Inspected 3/27/24
- Mileage 23047

[VIN & Dealer Code Check]

- Run and print Vehicle History Report and attach Meets STD
- Run a Techstream Health Check Meets STD
- Check outstanding Recalls and SSCs Meets STD

[Road Test]

- Cold engine operation performs properly Meets STD
- Throttle operates properly during cold start Meets STD
- Vehicle operates properly during warm-up conditions Meets STD
- Engine performs properly during operating temperature Meets STD
- Engine reaches normal operating temperature Meets STD
- Engine fan(s) operate properly Meets STD
- Brake pedal free play and travel within specifications Meets STD
- No abnormal vibrations and noises during brake applications Meets STD
- ABS operates properly Meets STD
- Parking brake operates properly and within spec Meets STD
- Seat belt material condition Meets STD
- Seat belts operate properly Meets STD
- Transmission/clutch operates smoothly Meets STD
- Auto transmission operates properly during cold temp Meets STD
- Auto transmission operates properly during operating temp Meets STD
- Steering normal in lock-to-lock turning Meets STD
- Steering wheel centered in straight-line driving Meets STD
- Vehicle tracks and drives straight on level surface Meets STD
- Tilt and telescope steering operates properly Meets STD
- Front wiper operates properly in all modes Meets STD
- Rear wiper operates properly in all modes NA
- Washer fluid sprays properly Meets STD

- Wiper blades clear glass properly **Meets STD**
- Wiper blades return to correct position when off **Meets STD**
- Speedometer functions properly **Meets STD**
- Odometer registers mileage in every mode **Meets STD**
- Cruise control operates properly **Meets STD**
- Heater operates properly **Meets STD**
- A/C operates properly **Meets STD**
- No abnormal noise or vibration from engine **Meets STD**
- No excessive wind or road noise **Meets STD**
- No abnormal tire vibration or wheel shimmy **Meets STD**
- No abnormal squeaks/rattles within interior **Meets STD**

[Frame, Structure & Underbody]

- Frame/Unibody condition **Meets STD**
- Panel alignment and fit **Meets STD**
- Lower body and underbody condition **Meets STD**
- Suspension-related items for proper performance **Meets STD**
- Inspect struts/shocks for leaks and wear **Meets STD**
- Power steering system operate properly no leaks **Meets STD**
- Wheel covers secure and reasonably free of damage **NA**
- Tires inflated to spec / free of defect and damage **Meets STD**
- Min of 5/32" tread depth remaining **Meets STD**
- All tires of same brand, model, size and rating **Adjust/Repair**
- Brake calipers and lines operate properly no damage **Meets STD**
- Brake system contains all needed equipment **Meets STD**
- Brake pad/shoe linings have minimum of 50% remaining **Meets STD**
- Brake rotors/drums in spec with no abnormal grooving or color **Meets STD**
- Exhaust system properly secured with no leaks **Meets STD**
- Engine/trans mounts with no signs of wear **Meets STD**
- Drive/axle shafts operate properly with no damage **Meets STD**
- CV joints/boots operate properly with no signs of wear **Meets STD**
- Inspect engine for fluid leaks **Meets STD**
- Inspect transmission case and pan for leaks **Meets STD**
- Differential fluid level correct with no leaks **Meets STD**

[Emissions & State Inspection]

- Perform emissions test and/or state inspec, if req **NA**

[Under Hood]

- Drive belts and hoses free of cracks and damage **Meets STD**
- Confirm under-hood labels and decals **Meets STD**
- Air filter in good condition **Meets STD**
- Battery has no visible damage **Meets STD**
- Perform battery check with Midtronics GR8 **Meets STD**
- Battery posts and cables free of corrosion and damage **Meets STD**
- Battery properly sized and secure **Meets STD**

- Charging system operating properly and within spec
- Engine coolant level with spec **Meets STD**
- Coolant specific gravity set to -31 deg F **Meets STD**
- Change engine oil and filter **Meets STD**
- Check for evidence of oil gel **Meets STD**
- Oil, brake, clutch, trans, transf case, power steering, washer fluid at proper levels **Meets STD**
- Under hood fluids clear and uncontaminated **Meets STD**

[Functional & Walkaround]

- Owner's manual and TCUV Warr Supplement **Meets STD**
- Fuel gauge operational **Meets STD**
- Battery voltage gauge operational **Meets STD**
- Engine temperature gauge operational **Meets STD**
- Horn operates properly **Meets STD**
- Airbag(s) present with no evidence of deployment **Meets STD**
- Headlights properly aligned **Meets STD**
- High and low beams operate properly **Meets STD**
- Tail lights operate properly **Meets STD**
- Side marker lights operate properly **Meets STD**
- Backup lights operate properly **Meets STD**
- License plate lights operate properly **Meets STD**
- No cracked or broken lenses of exterior lights **Meets STD**
- Instrument panel/warning lights operate properly **Meets STD**
- HVAC panel/lights operate properly **Meets STD**
- Instrument panel dimmer operates properly **Meets STD**
- Turn signals operate properly and self-cancel **Meets STD**
- Hazard flashers operate properly **Meets STD**
- Rear-view interior mirror operates properly **Meets STD**
- Exterior mirrors' operation and condition **Adjust/Repair**
- Remote mirror control operates properly **Meets STD**
- Glass free of cracks, stars and large chips **Meets STD**
- Window tinting clear and conforms to local reqs **Meets STD**
- Dome/courtesy lights operate with door cycles **Meets STD**
- Windows operate properly **Meets STD**
- Window locks operate properly **NA**
- Power windows operate from all switches **Meets STD**
- Audio/Cassette/CD/Aux system working properly **Meets STD**
- Speakers do not rattle at high volume and function properly **Meets STD**
- Antenna is present and functional **Meets STD**
- Clock operates properly **Meets STD**
- 12v ACC power output operates properly **Meets STD**
- Ashtrays (if equipped) are present and operate properly **NA**
- Headliner, sun visors, dash pad, upholstery, console, cup holders, trim panels and carpet are in place and in good condition **Meets STD**

- Driver floor mat is appropriate for vehicle, properly secured and not stacked on top of another **Meets STD**
- Doors open and close properly **Meets STD**
- Door locks, including child safety locks, operate properly **Meets STD**
- Remote keyless entry and smart key systems operate properly **Meets STD**
- Master key is present **Meets STD**
- Theft deterrent system operates properly **Meets STD**
- Seat adjustments and heater(s) operate properly **Meets STD**
- Memory seat control operates properly **NA**
- Headrests function properly **Meets STD**
- Defogger indicator light operates properly **Meets STD**
- Rear defogger operates properly **Meets STD**
- Luggage compartment light operation and trim **Meets STD**
- Luggage compartment is clean, free of debris and stains **Meets STD**
- Hood and luggage comp latches operate properly **Meets STD**
- Interior remote luggage comp release operates properly **Meets STD, Meets STD**
- Emergency trunk release operates properly **Meets STD**
- Fuel door release operates properly **Meets STD**
- Spare tire cover appearance and condition **Meets STD**
- Spare tire present **Meets STD**
- Spare has correct pressure and a min of 5/32" tread **Meets STD**
- No signs of damage to spare tire **Meets STD**
- Spare tire and storage areas are clean **Meets STD**
- Spare tire securely fastened **Meets STD**
- Jack and tools correct, present and secured **Adjust/Repair**
- Acceptable aftermarket items checked **Meets STD**
- Removal of unacceptable aftermarket items **Meets STD**

[Exterior Appearance]

- Body surface condition **Meets STD**
- Exterior is washed, clean and free of water spots **Meets STD**
- Paint is free of swirl marks and has an even, high luster **Meets STD**
- Paint is free of removable scratches **Meets STD**
- Paint is free of wax residue **Meets STD**
- Wheels/wheel covers are clean **Meets STD**
- Wheel wells are clean **Meets STD**
- Tires are clean and properly dressed **Meets STD**

[Engine Compartment]

- Compartment is clean **Meets STD**
- Under-hood heat insulator pad is clean **Meets STD**
- Engine and compartment are properly dressed **Meets STD**

[Interior Appearance]

- Interior is free of debris **Meets STD**
- Dash and vents are clean and properly dressed **Meets STD**
- All crevices are clean **Meets STD**

- Ashtrays and lighter are clean (if equipped) **Meets STD**
- Door jambs are clean **Meets STD**
- Glove box and console compartments are clean **Meets STD**
- Cabin air filter condition **Meets STD**
- Seats, carpets, floor mats and headliner free of stains **Meets STD**
- Free of odor, including heavy fragrance **Meets STD**
- Glass is clean and free of streaks **Meets STD**

[Exterior Repairs]

- Body is free of all dents **Meets STD**
- Body is reasonably free of dings **Meets STD**
- Paint is reasonably free of scratches and chips **Meets STD**
- Vehicle is free of improper paint repairs or mismatched color **Meets STD**
- Glass is free of improper repairs **Meets STD**
- Bumpers are free of cuts, gouges and mismatched paint **Meets STD**

[Interior Repairs]

- Interior leather, vinyl, plastic, carpet and fabric surfaces free of holes, rips, tears, excessive wear or fading **Meets STD**
- No evidence of previous improper wear interior repairs **Meets STD**

[Additional Inspection Items (where applicable)]

- "Fade-away" dome light operates properly **Meets STD**
- Sunroof/convertible top operates properly **NA**
- Seat heaters operate properly **Meets STD**
- Head unit software update **Meets STD**
- Nav system operates properly and mem system cleared **NA**
- Transfer case smoothly switches from 2WD to 4WD and back **NA**
- Truck bed in good condition **NA**
- Truck bed-liner in good condition and secured **NA**
- Tailgate operates properly **NA**
- Backup camera operates properly **Meets STD**
- Bluetooth searches for signal **Meets STD**
- SOS (Safety Connect) **NA**
- Lane Keep Assist operates properly **Meets STD**
- Dynamic Radar Cruise Control/Pre-Collision Systems operate correctly **Meets STD**
- Intelligent Parking Assist operates properly **Meets STD**

[Hybrid Components]

- Hybrid battery **NA**
- Battery control module **NA**
- Hybrid power management control module **NA**
- Electric motor/generator operates properly **NA**
- ECVT operates smoothly and properly **NA**
- Power inverter operates properly **NA**
- Inverter coolant level **NA**
- EV/Eco/Power modes operate properly **NA**

- Check transaxle park mechanism **NA**
- Multi-information display operates properly **NA**
- Touch Tracer display operates properly **NA**
- Hill Start Assist operates properly **NA**
- Remote A/C system (if equipped) operates properly **NA**
- Solar-powered vent system (if equipped) operates properly **NA**

Tread Depth (measured in 1/32")

- LF **10**
- RF **8**
- LR **6**
- RR **6**

Check Brake Linings (measured in millimeters)

- LF **8**
- RF **8**
- LR **8**
- RR **8**

Technician _____ Date _____

Service Manager _____ Date _____

Used Car Manager _____ Date _____

Customer _____ Date _____

Additional Service Recommendations

In the process of inspecting your vehicle for safety and reliability, your technician **Jaden K** made the following observations and recommends that you do the necessary repairs to resolve these issues.

Red: requires immediate attention.

Yellow: in need of attention soon.

[Other]: pass mirror skullcap is cracked and light is missing

Item Description

Speak with your service advisor for more information on this recommended service.

Reason



[Other]: spare tire jack is present, but tools are missing

Item Description

Speak with your service advisor for more information on this recommended service.

Reason



COMPLETED REPAIRS

RO# 6072926 - 4/3/2024 8:55 AM

SERVICE ADVISOR
James Cook
jrocktundra@gmail.com
(785) 539-7441

PREPARED FOR
INVENTORY: P7991

PRINTED - 4/3/2024
QUOTE EXPIRES - 5/3/2024
REPAIR FACILITY ID -

2023 FORD MUSTANG
1FA6P8TH2P5111111
Mileage 22,907

SERVICE NAME					COST
[Other]: pass mirror skullcap is cracked and light is missing (I)					
LABOR	0.90 hours at \$165.00 per hour				\$148.50
PARTS	Qty	Description	Number	Price	Total
	1	MIRROR ASSY	MAXMOTORS	\$720.80	\$720.80
Parts and labor sub total					\$869.30
[Other]: spare tire jack is present, but tools are missing (I)					
LABOR	0.00 hours at \$0.00 per hour				\$0.00
PARTS	Qty	Description	Number	Price	Total
	1	TOOL SET	MAXMOTORS	\$98.78	\$98.78
Parts and labor sub total					\$98.78

Total Labor	\$148.50
Total Parts	\$819.58
Subtotal	\$968.08
Shop Charges	\$34.00
Taxes	\$3.11
Total	\$1,005.19



Little Apple Cars
2828 Amherst Ave
Manhattan, KS 66502

(785) 539-7441